




S-CAMSHAFT-----EUROPEAN TYPE		
PICTURE	OEM.NO.	USED IN VEHICLES
	05.097.05.01.3 / 05.097.05.02.3	BPW
	05.097.05.47.3 / 05.097.05.48.3	BPW
	05.097.05.19.3 / 05.097.05.20.3	BPW
	05.097.05.21.3 / 05.097.05.22.3	BPW
	05.097.05.23.3 / 05.097.05.24.3	BPW
	05.097.05.25.3 / 05.097.05.26.3	BPW
	05.097.05.39.3 / 05.097.05.40.3	BPW
	05.097.05.27.3 / 05.097.05.28.3	BPW
	05.097.05.29.3 / 05.097.05.30.3	BPW
	05.097.05.55.3 / 05.097.05.56.3	BPW
	212 21 071 / 212 21 070	ROR
	212 21 195 / 212 21 194	ROR
	2.262.0257.02 / 2.262.0258.02	SAF
	2.262.0271.02 / 2.262.0272.02	SAF
	2.262.0283.02 / 2.262.0284.02	SAF
	2.262.0293.02 / 2.262.0294.02	SAF
	2.262.1102.02 / 2.262.1103.02	SAF
	6503391M / 6503390L	TRAILER
	A-JA-0476-003 / A-JA-0476-004	FRUEHAUF

S-CAMSHAFT REPAIR KIT-----EUROPEAN TYPE		
PICTURE	CROSS REF.	USED IN VEHICLES
	A9983	BPW
	09.801.06.09.1	BPW
	09.801.02.22.0	BPW
	AXL122	ROR
	AXL132	ROR
	AXL140	ROR
	A2335	ROR
	A1665	ROR
	A1809	ROR
	3268003400	SAF
	3268003500	SAF
	3268003700	SAF
	A1643	YORK
	A8258	TRAILER
	A5925	FRUEHAUF

S-CAMSHAFT-----USA TYPE		
PICTURE	OEM.NO.	USED IN VEHICLES
	M16WK104-25/M16WK105-25	SPICER
	7-2395/7-2396	EATON
	AXA-000420-001/AXA-000420-002	FRUEHAUF
	202100-236R/202100-236L	TRAILER
	M16WK104-17/M16WK105-17	SPICER
	R607075/R607076	MERITOR
	R607091/R607092	MERITOR
	AXA-000420-003/AXA-000420-004	FRUEHAUF
	M16WKL25-236/M16WKR25-236	SPICER
	2210C6867/2210B6866	MERITOR
	2210E6869/2210D6868	MERITOR
	2210A7099/2210H7522	MERITOR
	2210T8158/2210S8157	MERITOR
	2210R8165/2210Q8155	MERITOR
	2210V8160/2210U8159	MERITOR
	2210N6410/2210P6412	TRAILER
	2210A6995/2210B7594	MERITOR
	2210A6943/2210V7536F	MERITOR
	2210Q7427/2210P7426	MERITOR
	R607070/R607069	MERITOR

S-CAMSHAFT REPAIR KIT-----USA TYPE		
PICTURE	CROSS REF.	USED IN VEHICLES
	E-9079HD M-K88	MERITOR
	E-2469 R615010	SPICER AND STANDART FORGE
	E-5513 KIT8033	MERITOR
	E-2088A KIT8046	MERITOR
	E-2088AHD	MERITOR
	E-2291 KIT9036	MERITOR
	E-9790A M-K103 R615019	SPICER
	E-2680 R615007	SPICER
	E-2680B M-K17 KIT9078	MERITOR
	E-2383 KIT970	MERITOR
	E-3520A M-K61 KIT8048	MERITOR
	E-3520AHD	MERITOR
	E-3993B M-K81 KIT8042	MERITOR
	E-1357A KIT9037	MERITOR
	E-2287 M-K23 R615008	SPICER AND STANDART FORGE
	E-2087 R615009	SPICER AND STANDART FORGE
	E-2090 M-K20 R615005	FRUEHAUF
	E-9791HD R615020	HENDRICKSON
	E-2696A M-K63 R615004	EATON
	E-2125 R615004=2	EATON

S-CAMSHAFT-----OTHERS		
PICTURE	OEM.NO.	USED IN VEHICLES
 	C3970366	CUMMINS
	3053525	CUMMINS
	3923478	CUMMINS
	3949042	CUMMINS
	199180	CUMMINS
	7200	HINO
	286078-D	HERCULES
	256253-D	HERCULES
	740-1006015	KAMAZ
	13511-35011	BMW
	3141526A/4	PERKINS
	3660500301	BENZ
	A09-101-001	VOLVO
	479610-8 / 479610 / 1545071	VOLVO
	3354210336 / 3354210436	BENZ
	6234210136 / 6234210236	BENZ
	6234230136 / 6234230236	BENZ
	6524230036 / 6524230136	BENZ
	6254230136 / 6254230036	BENZ
	3964230036 / 3964230136	BENZ
	3574230236 / 3574230236	BENZ
	3414237536 / 3414237436	BENZ
	6244230136 / 6244230036	BENZ
	3054231636 / 3054231736	BENZ
	3444230536 / 3444230436	BENZ
	3854230236 / 3854230136	BENZ
	3834230936 / 3834231036	BENZ
	3834230736 / 3834230836	BENZ
	3834230536 / 3834230636	BENZ
	3834230336 / 3834230436	BENZ
	3834230136 / 3834230236	BENZ
	3414231536 / 3414231436	BENZ
	3614232936 / 3614232836	BENZ
	3614233136 / 3614233036	BENZ
	3074230536 / 3074230436	BENZ
	3464231436 / 3464231336	BENZ
	3014230236 / 3014230136	BENZ
	3074230336 / 3074230236	BENZ
	3464231236 / 3464231136	BENZ
	3464230936 / 3464231036	BENZ
3054231336 / 3054231336	BENZ	